


HOLLAND
Electronics LLC **CGT-FBR**



F-Connector Installation Instructions



1
Hold the F Connector and CGT-FBR Tool in each hand



2
Insert the F connector onto the small end of the tool



3
Guide your stripped coax into the end of the small tube on tool
(This tube will guide your center conductor safely through connector)



4
Firmly press the cable, ensuring the connector is inserted entirely




5
The connector is ready to be terminated with the Compression Tool

HOLLAND
Electronics LLC **CGT-FBR**




BNC-Connector Installation Instructions



Hold the BNC Connector and CGT-FBR Tool in each hand



Insert the BNC connector into the large end of the tool



Guide your stripped coax into the end of the BNC connector



Firmly press the cable, ensuring the connector is inserted entirely




The connector is ready to be terminated with the Compression Tool

HOLLAND
Electronics LLC **CGT-FBR**




RCA-Connector Installation Instructions



Hold the RCA Connector and CGT-FBR Tool in each hand



Insert the RCA connector into the large end of the tool



Guide your stripped coax into the end of the RCA connector



Firmly press the cable, ensuring the connector is inserted entirely



The connector is ready to be terminated with the Compression Tool



Other Recommended Connector Tool Products by Holland Electronics

Compression Connector Tool
P/N: CT-FBR



Coax Strip Tool
P/N: CPT-6590



Connector Installation Tool
P/N: CIT-1



P/N: TSTL-3AKIT